



I n n e r S p a c e S y s t e m s  
C o r p

Correspondence:                      Shipping:  
P.O. Box 449                              1714 Midway Court  
Centralia, WA 98531 USA      Centralia, WA 98531 USA  
Phone: (+001)360.330.9018      FAX: (+001)360.330.9019

March 20, 2008

On 21 February, 2006, ISC performed preliminary testing on the Megalodon Closed Circuit Rebreather at the Health & Safety Laboratory in Buxton, UK. The HSL is an agency of the Health and Safety Executive. Purpose of the testing session was to determine performance of the Megalodon based on the CCR rebreather standards, EN14143. Here are some of the pictures taken on this trip.



**Photo 1 - Entrance Sign**



**Photo 2 - Facility view**



**Photo 3 - Main Gate facility view**



**Photo 4 - Appropriate safety warning signs**



**Photo 5 - ANSTI Breathing Machine Rebreather Test Chamber**



Photo 6 - The ANSTI Control Console



**Photo 7 - Cis Lunar Scrubber Packing - Fits MEG**




**Photo 8 - MEG setup in test chamber**




**Photo 9 - Packing Prism Radial Scrubber for MEG testing**





**Photo 10 - Scrubber Fleet - L to R: ISC 7.5 lb Radial, Cis Lunar 7 lb Radial, Prism Radial, & ISC 5.5 lb Axial**



**Photo 11 – HSL Investigator @ ANSTI test console, MEG under Test**